



County of Riverside  
**DEPARTMENT OF ENVIRONMENTAL HEALTH**

P.O. BOX 7909 • RIVERSIDE, CA 92513-7909

STEVE VAN STOCKUM, DIRECTOR

## WATER SYSTEM INSPECTION REPORT

STATE ID# 1790

DATE: March 8, 2018

NAME: **Weber Valley Heights Association**

LOCATION: 44135 Perryman Lane Hemet, CA 94544

MAILING ADDRESS: Jeff Hall 36455 E. Benton Road, Hemet, CA 92543  
Robert Franko & Debbie St. Pierre 44135 Perryman Lane Hemet, CA 92544

OWNER/OPERATOR: President Jeff Hall 951-767-7072 home, 951-313-2249 cell  
Robert Franko, Vice President 951-764-5081  
Secretary / Treasurer Deborah St. Pierre 951-764-5059  
Dan Spears, Maintenance 909-770-0852

WA0000287

FA0001407

### TYPE OF SYSTEM

This is a State Small water system with two wells and 2 pressure zones. There are 6 connections on each well.

A joint inspection was conducted on March 8 2018 by Heidi Barrios, REHS and Matt Riha, Supervising REHS. The following were present during this inspection: Deborah St. Pierre, Robert Franko, Phillip Alleano (member), Brian Bealer, Code Enforcement, and Sheriff's Deputy Schroeder.

### SOURCES OF WATER AND STORAGE FACILITIES

#### Well No. 1

- GPS: 33 Degrees 35.525 N and 116 Degrees 53.888 W
- Water system pressure 150 psi.
- Bacteriological testing is current and meets standards
- 2 tanks are observed to be in good condition.

#### Well No. 2

- GPS: 33 Degrees 35.527 N and 116 Degrees 53.544 W
- Water pressure was not observed
- TDS taken at Tank 370 ppm
- Bacteriological testing is current and meets standards.
- Tank is in good condition

### CHEMICAL QUALITY

Location	Sample Date	Nitrate as N (µg/L)	
Well 1	10/26/16	2.7	
Well 2	10/26/16	2.6	
Well 1	10/24/18	6.1	
Well 2	10/24/18	2.0	

## **BACTERIOLOGICAL QUALITY**

Bacteriological sampling has been satisfactory for the past year.

## **CORRECTIONS & RECOMMENDATIONS:**

1. Recommend repair of the float switch and associated electrical conduit between well 1 and the tank. Remove the unapproved Romex wiring on the side of the tank. Operator is currently manually controlling tank volume.
2. Due to the age and type of tanks, it is not feasible to install a locking mechanism on the tank lids. Recommend installing a locked enclosure for the holding tanks.

Heidi Barrios, MBA, REHS



Heidi Barrios, MBA, REHS, IH, CSST  
Riverside County Department of Environmental  
Health  
Land Use Division and Water Resource  
Management  
Phone #: 951-955-8980  
E-mail: [hbarrios@rivco.org](mailto:hbarrios@rivco.org)  
[www.rivcoeh.org](http://www.rivcoeh.org)